F16.1






FIG. 2A

F1G.2B



PUT INTO TRACK
APPLY SOLVENT





SPINNING

FIG.2C



SPINNING





PUT INTO BALANCE AND WEIGHT OBTAIN WEIGHT W2

PUT INTO BALANCE AND WEIGHT OBTAIN WEIGHT WI

BAKE, REMOVE SOLVENT




FIG.2E